
Bus Interface Circuit

These messages are Test Failure messages for the Bus Interface Circuit (BIC) that provides the interfaces and protocols for the Inter Processor Bus (IPB).

BIC messages

BIC0000 x y	BIC x y register read/write/verify test failed.
BIC0001 x y	BIC x y BIC/SRA interface IPBINT test failed.
BIC0002 x y	BIC x y BIC/SRA interface PARERR test failed.
BIC0003 x y	BIC x y arbitration test failed.
BIC0004 x y	BIC x y IRQ test failed.
BIC0005 x y	BIC x y timer test failed.
BIC0006 x y	BIC x y IOP event interrupt test failed.
BIC0007 x y	BIC x y CP self event interrupt test failed.
BIC0008 x y	BIC x y initial conditions failure.
BIC0009 x y	BIC x y window test failure.
BIC0010 x y	BIC x y testing the ASIC.
BIC0011 x y	BIC x y card failed one or more BIC test.

Action: Reseat or replace the card.